



















New product catalogue  
Realese May 2009

No.	Fig.	Part no.	Wire range	Material	MOQ	Terminals	Info
1		<b>3MTN08FB02BK</b>	N/A	PA66	100	6630901PSS 	<b>Car Audio</b>
2		<b>3MTN08FB02BR</b>	N/A	PBT	100	6630901PSS 	<b>Car Audio</b>
3		<b>3MTN08MB02BK</b>	N/A	PA66	100	6605152BWS 	<b>Car Audio</b>

4		<b>3MTN08MB02BR</b>	N/A	PA66	100	6605152BWS 	<b>Car Audio</b>
5		<b>3TSR02MGY06GR</b>	N/A	PBT	100	6617307BSS 	<b>Engine nozzle connector</b>
6		<b>3DLR02MGY06BK</b>	N/A	PBT	100	6617337BSS 	<b>Engine nozzle connector</b>

7		<b>3RG12FB02BK</b>	N/A	PA66	30	6604406BS2 	Windows/headlight switch
8		<b>6836301KSS</b>	3.0mm <sup>2</sup>	Cooper Alloys	2000	6617236/6617237/6617238	<b>TOYOTA</b>
9		<b>6805804KSS</b>	0.22~0.35mm <sup>2</sup>	Cooper Alloys	8000	N/A	<b>TOYOTA COROLLA</b>
10		<b>6805904KSS</b>	0.22~0.35mm <sup>2</sup>	Cooper Alloys	8000	N/A	<b>TOYOTA COROLLA</b>

11		<b>6881002PS0</b>	1.25mm <sup>2</sup>	Phosphor Bronze	5000	N/A	<b>AC Power Cord Socket</b>
12		<b>6604903BS0</b>	0.3~0.5mm <sup>2</sup>	Brass	3000	N/A	<b>Car wire Harness</b>
13		<b>6853102BSS</b>	0.8~1.3mm <sup>2</sup>	Brass	5000	N/A	<b>Motorcycle</b>
14		<b>6629012PLN</b>	N/A	Phosphor Bronze	500	N/A	<b>Medical use of terminal</b>
15		<b>6878627CLS</b>	N/A	Cooper	1000	N/A	<b>Office furniture outlet</b>

16		<b>6682196BS0</b>	0.85~1.25mm <sup>2</sup>	Brass	5000	N/A	<b>AC Power Cord Socket</b>
17		<b>6602516BS2</b>	0.85~1.25mm <sup>2</sup>	Brass	2500	N/A	<b>Snow removal vehicles wiring harness</b>

More information  
 Marcin Władyko / Sales dept.  
[m.wladyko@automotive-connectors.pl](mailto:m.wladyko@automotive-connectors.pl)